



45<sup>TH</sup> **TURBOMACHINERY** & 32<sup>ND</sup> **PUMP** SYMPOSIA  
HOUSTON, TEXAS | SEPTEMBER 12 – 15, 2016  
GEORGE R. BROWN CONVENTION CENTER

# Resolving Cyclic Vibration on an Instrument Air Compressor

**Amit Sharma**

Lead Engineer, Machinery Diagnostics Services  
GE Oil & Gas- Digital Solutions, Bently Nevada

**Nicolas Peton**

Global Director, Machinery Diagnostics Services  
GE Oil & Gas- Digital Solutions, Bently Nevada



imagination at work



TEXAS A&M  
UNIVERSITY



# Authors

- **Amit Sharma**

- Lead Engineer, GE-BN, Machinery Diagnostics Services, Abu Dhabi, U.A.E.
- With GE-BN Machinery Diagnostics Services Group since 2007
- Project Engineer- Rockwell Automation-Entek IRD

- **Nicolas Peton**

- Global Director, GE-BN, Machinery Diagnostics Services, Nantes France
- With GE-BN Machinery Diagnostics Services Group since 2006
- Worldwide Startup Activities Site-In-Charge, Alstom (Steam Turbine) & Cryostar ( expander/compressor)
- Operation & Maintenance Engineer- PPG Industry, USA
- Mechanical/Acoustical Research Engineer, Technion, Haifa and TU Berlin

## **Case Study on Resolving Cyclic Vibration on an Instrument Air Compressor Train**

Instrument Air Compressors are considered critical equipment in the plants, supplying compressed air to the instrumentations in the field. This case study focuses on cyclic vibration phenomena observed in the 2<sup>nd</sup> and 3<sup>rd</sup> stages of an Instrument Air Compressor, part of an Integral Gear Compressor train driven by a motor. The machine train is equipped with an online vibration monitoring and protection system with online diagnosis software, which was used to diagnose the phenomena & forward path for the resolution.


# Content

- Problem Statement
- Machine Train Details
- Observation/Analysis
- Conclusions & Recommendations
- Machine Inspection Findings
- Corrective Actions / Lesson Learned

## Problem Statement

- 3-stage integrally-gearred instrument air compressor train experienced cyclic vibration.
- Phenomena noticed on 2<sup>nd</sup> & 3<sup>rd</sup> stage bearings with first observation during April 2013 and persisted till major overhauling in September 2014.
- From September 2013 onwards, the vibration amplitudes of 3<sup>rd</sup> stage intermittently reached alarm limits & Machine availability became a concern for the customer.

# Machine Train Details



## Operating Speeds

### **Pinions**

1<sup>st</sup> Stage - 35793 rpm

2<sup>nd</sup> Stage - 52063 rpm

3<sup>rd</sup> Stage - 52063 rpm

### **Motor/Bull Gear Speed**

2975 rpm



### **Critical Speeds**

1<sup>st</sup> Stage - 21000 rpm

2<sup>nd</sup> /3<sup>rd</sup> Stage - 30800 rpm

# Observations/Analysis


## Direct & 1X Vibration Trend for 3<sup>rd</sup> Stage:



*Abnormal periodic fluctuations of Direct and 1X vibration, repeating each cycle at 1 minute interval.*

# Observations/Analysis

## 1X Polar Plot of 3<sup>rd</sup> Stage Bearing: Steady State Condition





*Abnormal 360-degree 1X phase angle revolutions*



# Observations/Analysis



## Direct & 1X Vibration Trend of 2<sup>nd</sup> Stage:



*Abnormal periodic fluctuations of Direct and 1X vibration, repeating each cycle at 1 minute interval*

# Observations/Analysis


## 1X Polar Plot of 2<sup>nd</sup> Stage Bearing: Steady State Condition



*1X phase angle observed to revolve at one particular quadrant.*

# Observations/Analysis


## Transient & Steady State- 1X Polar Plots of 2<sup>nd</sup> Stage Bearing:



- Transient condition appears normal, where machine reached operating speed with normal behavior
- 1X Phase revolution occurs just after reaching operating speed during steady state

# Observations/Analysis

## Transient & Steady State- 1X Polar Plots of 3<sup>rd</sup> Stage Bearing:




-Transient condition appears normal, where machine reached operating speed with normal behavior

-1X Phase revolution occurs just after reaching operating speed during steady state

# Observations/Analysis

## Shaft Centerline Plots



*Stage-2 & 3 rotor shows abnormal shaft centerline movement.*

*Suspected rubbing with the carbon seals on stage 2 & 3 as evidenced from the rotor bouncing at steady state, particularly on stage 3.*

# Conclusions & Recommendations

## **Conclusions:**

- Detailed analysis indicates that the vibration is real and not due to instrumentation error.
- Third & Second Stage bearings show typical rub induced vibrations that can be sufficient enough to create localized heating of the rotor causing it to bow.
- The shaft centerline lift during transient condition indicated abnormal gear forces due to misaligned gear assembly causing rubbing of rotor with carbon seals.

## **Recommendations:**

- Investigate the qualitative analysis of oil ( viscosity, moisture etc.)
- Verify the alignment condition of the gear assembly with the protocol values.

## Machine Inspection Findings



*Brownish oil burn marks on 2<sup>nd</sup> & 3<sup>rd</sup> stage bearings and rubbing marks on the pinion rotors observed.*

### Suspected Reasons:-

- *Carbon Seals rub due to mis-alignment across the gears.*
- *Burnishing is suspected due to shear stresses in the oil causing high temperature.*

## Corrective Actions / Lesson Learned

### **Corrective actions:**

- All the pinion rotors were replaced with new rotors.
- All the bearings were replaced.
- Alignment of the integral gear assembly was carried out.
- Lubricating oil was replaced per the recommendation from OEM. The oil type was changed in terms of viscosity (higher to lower viscosity).


### **Lessons learned:**

- Oil degradation can lead to shear stresses in the oil lubricant. Hence monitoring of oil quality is also an essential activity.
- Availability of historical information from online condition monitoring system enabled identification of the root cause.




# Post Maintenance Data Plots

## 1X Polar Plots of 2<sup>nd</sup> and 3<sup>rd</sup> Stage bearings:



Stage 2




Stage 3

*Stable 1X amplitudes/1X phase observed at stage 2 & 3 bearings.*


# Post Maintenance Data Plots

## Shaft Centerline Plots

Stage 1



Stage 2



Stage 3

*Normal Shaft Centerline lift observed for all of the pinion rotors after the corrective actions.*

**QUESTIONS...**